

<Centre Post and Hole in Main Beam 10 Sep 19.jpg>

When the lead was removed it exposed a large hole which threatens the integrity of the main beam. This will have to be spliced with a steel sleeve. The top of the centre post is rotten and will have to be removed. The following characters were found carved on the side of the beam:
1775 DIGBY WORT

<Tower Skeleton 10 Sep 19.jpg>

A skeleton of a bird. There is no sign of skin or feathers, so it must be old.

<Tower lead stripped 10 Sep 19.jpg>

The view from below the bell chamber. Fortunately most of these boards are still sound in spite of their age..

<Rotten Tower joist 10 Sep 19.jpg>

Some of the ends of the joists resting on the tower walls have rotted and need repair.

Peter Booth

01985 845379

Tower Society in support of
Church of St Mary The Virgin, LCC
Kilminster
Warminster
Wiltshire BA12 6RD